

INCIDENT: Sprinkler System Suspected of E-Coli Contamination
LOCATION: Corpus Christi, Texas
SOURCE:
DATE OF INCIDENT: 7/27/2015

Corpus Christi utility crews pinpoint the source of the E-coli contamination, their investigation found that an absent or failing backflow prevention device on a sprinkler system in the Flour Bluff area. The devices prevent water that enters private irrigation lines from re-entering the city's water lines and potentially leading to a contamination.