

Errata

BTL Test Package 15.0 (applied to create 15.0.05)

8/28/2017

This document lists all known *errata* to BTL Test Package 15.0 as of the above date. Each entry is first cited by clause, then page number, except where an erratum covers more than one clause.

1. One suggested change in another area was mentioned as suitable for errata: move AE-INFO-A and AE-INFO-B within Test Plan and Checklist to locate them just after AE-ESUM-B, before the four Event Log sections, and renumber existing 5.10 through 5.15 to follow after them, so that summarization services are in sections in the same order as BIBBs K.2.6 through K.2.11
2. Add 'object' to end of title in checklists for new objects added.
3. Resolve difference between Global Group Checklist and Test Plan entry for 'Supports DS-RP-A for retrieving member values'
4. Remove K.1.X1 BIBB - Data Sharing - View - A (DS-V-A) since the reprint has the correct information.
5. Remove K.1.X4 BIBB - Data Sharing - Modify - A (DS-M-A) since the reprint has the correct information.
6. Re-arranged T-V-A in Checklist to match TP.
7. Re-arranged the T-AMVR-A and T-ATR-A in Checklist to match TP.
8. In DM-TM-A changed 'an CharacterString' to be 'a CharacterString' in TP.
9. Updated the 'External Reference' to include addenda ar in Test Plan document as per WID1073. Removes references to 135.1-2009, 135.1-2011, 135-2008, 135-2010, and adds references to addenda ar.
10. Changed reference in Base Requirements for EPICS Consistency Tests from 135.1 to BTL Specified Tests.
11. Fixed reference to test 14.1.10 to be BTL vs 135.1.
12. Fixed reference to test 10.7.2 to be BTL vs 135.1.
- ~~13. Changed reference for test 7.3.2.X38.1.3 to be BTL vs 135.1.~~
14. Added 'Reason for Change' to newly added tests to the BTL Specified Tests document.
15. Removed the NF, AE, Channel, and Lighting Output object from DM-OCD-A checklist as they were not in the Test Plan and we don't support those objects yet.
16. Modified Global Group Object, Base Requirements description :
From: Base requirements must be met by any IUT claiming conformance to this BIBB.
To: Base requirements must be met by any IUT that can contain Global Group objects.
17. In BTL Test Plan, changed reference for 9.10.2.1 The Monitored Object Does Not Support COV Notification, from 135.1 to BTL per 14.0b that made changes to this test.
18. In BTL Test Plan, changed reference for 7.3.1.11 Acked Transition Tests, from 135.1 to BTL per 14.0b that made changes to this test.
19. In BTL Specified Tests, Modified 7.3.2.24.19 Trigger Verification Test to show correct differences between current 135.1-2013 version and new BTL version.

20. In BTL Test Plan, updated all remaining references to test 8.21.9 Presents Log Records from 135.1 to the new BTL Specified Test version. (Addenda c only had a few).
21. In BTL Specified Tests, removed all change markings (strike through and italic) from new test 7.3.1.7.X1 COV_Resubscription_Interval Test. New tests don't have change markings.
22. In BTL Checklist, added Notification Forwarder Object. Existed in Test Plan document.
23. In BTL Test Plan, fixed title case for DM-TM-A and DM-TM-B entries.
24. In BTL Test Plan and BTL Checklist, updated the wording of the following section from: Can Fallback to ReadProperty Based on Peer's ServicesSupported to Can Fallback to ReadProperty Based on Protocol_Services_Supported.
25. In BTL Test Plan, updated the supporting paragraph to section 'Can Fallback to ReadPropertyBased on Protocol_Services_Supported' to use 'Protocol_Services_Supported' instead of 'ServicesSupported'.
26. In BTL Specified Tests, added the change tracking (strikethrough and italic) for the EPICS Consistency Test changes to the 135.1-2013 version.
27. In BTL Test Plan, COV Unsubscribed-A, modified title case for sections. Modified BACnetObjectIdentifier vs Object Identifier so that Checklist and Test Plan sections match. Re-ordered so that the Checklist and Test Plan match.
28. In BTL Test Plan, Changed title case to sections in DS-COVP-A.
29. In BTL Specified Tests, renumbered 8.11.4.X tests to be consistent.
30. In BTL Checklist, changed wording of superscript 2 in Device Object to be consistent with all other references to protocol revision.
31. In BTL Test Plan, modified heading of DS-COVP-A to match checklist version.
32. In BTL Test Plan, updated test references for 7.3.2.21.3.5 and 6 from 135.1 to BTL.
33. In BTL Test Plan, Change the Global Group Object Base Requirement section to refer to test 7.2.3 from BTL and not from 135.1.
34. In BTL Specified Tests, renumbered test steps for 8.4.X9 CHANGE_OF_RELIABILITY with COMMUNICATION_FAILURE.
35. In BTL Specified Tests, modified test reference in Notes to Tester for test 8.5.X8 to refer to the correct test. 8.4.X8 vs 8.4.X1.

15.0.06

36. In BTL Test Plan fixed the heading numbering for section 5.1 AE-N-A, the last two entries did not get renumbered when we added the new EXTENDED entry into the list.
37. In BTL Test Plan, section 4.9.1 the Test Conditionality of test 9.2.2.1 was changed from "Must be executed supports" to "Must be executed if IUT supports".
38. In BTL Test Plan, found and fixed all references to "As pe BTL Specified Tests" to "As per BTL Specified Tests". (8 instances)
39. In BTL Test Plan, Section in 5.11 was renumbered from 5.15.2 to 5.11.2.
40. In BTL Test Plan, Replaced where we references 135.1 test and BTL Specified Tests with *ASHRAE 135.1-2013*. Section 8.25, 8.26

15.0.07

41. In BTL Specified Tests and BTL Test Plan, Replaced 8.11.4.X* - test numbers with 8.11.X1.* test numbers. This will show that this is a new section and should be renumbered when it merged into 135.1.

42. In BTL Test Plan, Removed test reference in section 10.1.2 Routes Packets between Physical BACnet LANs for test 10.2.6 Execute Initialize-Routing-Table. This will be corrected and put back in a later addenda.
43. In BTL Test Plan, Remove test reference BTL - 8.4.X7.5 CHANGE_OF_RELIABILITY with the FAULT_STATUS_FLAGS Algorithm from section 3.37.20 Supports Reliability Evaluation. This will be added back when in a followup addenda when the test is ready for publication.
44. In BTL Test Plan and Checklist, remove the 'supports read-only Recipient_List Properties' item from Notification Class Object.
45. In BTL Test Plan and Checklist, remove the Notification Forwarder Object.
46. In BTL Test Plan and Checklist, remove the 'supports Network Forwarder Objects' and 'supports Writable Recipient_List Properties' from the AE-N-E-B section.
47. In BTL Test Plan and Checklist, remove Notification Forwarder, Alert Enrollment, Lighting Object, and Channel from DM-OCD-A.

15.0.8

48. In BTL Test Plan, Checklist remove section Global Group 'Supports Reliability Evaluation'.
49. In BTL Specified Tests, remove test 8.4.X9.

15.0.9

50. In BTL Test Plan, Fixed test references for Supports User Initiated Abort Backup and Supports User Initiated Abort Restore sections to reference the correct test.

15.0.10

51. In BTL Test Plan, fixed spelling error 'wich' with 'which'.
52. In BTL Test Plan, fixed typo 'bythe' with 'by the'.

15.0.11

53. Getting Started Guide, rebuilt the Table of Contents.
54. In BTL Manual Testing, removed spaces between 3.1 and 3.2 on page 9.
55. In BTL Specified Tests, pg 63, remove yellow highlight
56. In BTL Specified Tests, pg 77, add closing } for test 7.3.2.21.3.X9 for step 1.
57. In BTL Specified Tests-15.0.final.pdf – page 210 test 12.1.3.3 step 3, we should list 115200 since it went in at PR-12.