



Compatible N95 respirators that are visually soiled or damaged should not be collected for decontamination and will be disposed of and not returned after decontamination.

1. Label your own individual compatible N95 respirator using a permanent marker; do not label others' or ask others to label for you.
2. Labeling should be legibly written on the outside OR inside of each compatible N95 respirator, as shown below.
3. Label ALL compatible N95 respirators with the three-digit site code and 2-digit location identifier provided below.
4. Place your compatible N95 respirator in the collection bag provided by your healthcare facility at a designated collection station at your facility.



